

EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S1	0	fail\$safe near6 clock near6 switch\$over	US-PGPUB; USPAT; EPO; IBM_TDB	OR	OFF	2006/09/21 18:36
S2	33477	clock near6 (switch\$over switch switching switches)	US-PGPUB; USPAT; EPO; IBM_TDB	OR	OFF	2006/09/20 14:54
S3	320	clock near6 (switch\$over)	US-PGPUB; USPAT; EPO; IBM_TDB	OR	OFF	2006/09/20 14:55
S4	4391	713/400-601.ccls.	US-PGPUB; USPAT; EPO; IBM_TDB	OR	OFF	2006/09/20 14:55
S5	33	S3 and S4	US-PGPUB; USPAT; EPO; IBM_TDB	OR	OFF	2006/09/20 15:32
S6	1	"6292045".pn.	US-PGPUB; USPAT; EPO; IBM_TDB	OR	OFF	2006/09/20 15:07
S7	20807	micro\$controller near10 (cpu processor)	US-PGPUB; USPAT; EPO; IBM_TDB	OR	OFF	2006/09/20 15:39
S8	65829	(first primary master) near3 clock	US-PGPUB; USPAT; EPO; IBM_TDB	OR	OFF	2006/09/20 15:29
S9	66	S7 same S8	US-PGPUB; USPAT; EPO; IBM_TDB	OR	OFF	2006/09/20 15:40
S10	12	S2 and S9	US-PGPUB; USPAT; EPO; IBM_TDB	OR	OFF	2006/09/20 15:29
S11	4	S9 and S4	US-PGPUB; USPAT; EPO; IBM_TDB	OR	OFF	2006/09/20 15:40

EAST Search History

S12	91499	(micro\$controller micro\$processor) near10 (cpu processor)	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/20 15:40
S13	120671	(micro\$controller micro\$processor) same (cpu processor)	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/20 15:40
S14	627	S13 same S8	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/20 15:40
S15	70	S14 and S4	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/20 15:41
S16	8	zilog\$.as. and S2	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/20 16:50
S17	1	"6845454".pn.	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/21 10:55
S18	29	(disabling near6 (detection detector)) and 713/300-340.ccls.	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/21 17:35
S19	13	((disabling near6 (detection detector)) same clock) and 713/300-340.ccls.	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/21 17:37
S20	20	((power\$3 near3 (down off)) near6 (detection detector)) same clock) and 713/300-340.ccls.	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/21 17:52
S21	83	((((power\$3 turn\$3) near3 (on up)) near6 (oscillator dll pll clock)) same (fail\$3))	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/21 19:15
S22	32	((((power\$3 turn\$3) near3 (on up)) near6 (oscillator dll pll clock)) near10 (fail\$3))	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/21 17:55
S23	33	((((power\$3 turn\$3) near3 (on up)) near6 (oscillator dll pll clock)) near10 (fail\$3 inadequate))	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/21 19:30

EAST Search History

S24	83	<u>((power\$3 turn\$3) near3 (on up))</u> near6 (oscillator dll pll clock) same (fail\$3)	US-PGPUB; USPAT; EPO; IBM_TDB	OR	OFF	2006/09/21 18:37
S25	33	<u>((power\$3 turn\$3) near3 (on up))</u> near6 (oscillator dll pll clock) near10 (fail\$3 inadequate)	US-PGPUB; USPAT; EPO; IBM_TDB	OR	OFF	2006/09/21 18:37
S26	51	S24 not S25	US-PGPUB; USPAT; EPO; IBM_TDB	OR	OFF	2006/09/21 18:39
S27	84	<u>((power\$3 turn\$3) near3 (on up))</u> near6 (oscillator dll pll clock) same (fail\$3 inadequate)	US-PGPUB; USPAT; EPO; IBM_TDB	OR	OFF	2006/09/21 18:39
S28	51	S27 not S25	US-PGPUB; USPAT; EPO; IBM_TDB	OR	OFF	2006/09/21 18:39
S29	5318	(oscillator dll pll clock) near6 (fail\$3 inadequate)	US-PGPUB; USPAT; EPO; IBM_TDB	OR	OFF	2006/09/21 18:42
S30	32	S29 near10 ((power\$3 turn\$3) near3 (on up))	US-PGPUB; USPAT; EPO; IBM_TDB	OR	OFF	2006/09/21 18:45
S31	57	S29 and 713/300-340.ccls.	US-PGPUB; USPAT; EPO; IBM_TDB	OR	OFF	2006/09/21 18:43
S32	243	S29 and <u>((power\$3 turn\$3) near3 (on up))</u> near6 (oscillator dll pll clock)	US-PGPUB; USPAT; EPO; IBM_TDB	OR	OFF	2006/09/21 18:46
S33	49	S29 same <u>((power\$3 turn\$3) near3 (on up))</u> near6 (oscillator dll pll clock)	US-PGPUB; USPAT; EPO; IBM_TDB	OR	OFF	2006/09/21 18:46
S34	2259	<u>((power\$3 turn\$3) near3 (on up))</u> near6 (clock\$3)	US-PGPUB; USPAT; EPO; IBM_TDB	OR	OFF	2006/09/21 19:15
S35	102	S34 near10 (detect\$3 discover\$3)	US-PGPUB; USPAT; EPO; IBM_TDB	OR	OFF	2006/09/21 19:22

EAST Search History

S36	4	S35 near10 (fail\$3 inadequate lost unsuccess\$)	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/21 19:33
S37	34	((((power\$3 turn\$3) near3 (on up)) (power near2 applied)) near6 (oscillator dll pll clock)) near10 (fail\$3 inadequate))	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/21 19:31
S38	3255	((power\$3 turn\$3) near3 (on up)) (power near2 applied)) near6 (clock\$)	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/21 19:33
S39	32	S38 near10 (fail\$3 inadequate lost unsuccess\$)	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/21 19:33
S40	699	((power\$3 turn\$3) near3 (on up)) near10 (back\$up)) near10 (fail\$3 inadequate)	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 08:09
S41	5360	713/300-340.ccls.	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 08:07
S42	24	S40 and S41	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 08:10
S43	195	((power\$3 turn\$3) near3 (on up)) near10 (memory DRAM RAM)) near10 (fail\$3 inadequate)	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 08:12
S44	6	S43 and S41	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 08:10
S45	5	((power\$3 turn\$3) near3 (on up)) near10 (only near6 (necessary needed required))) near10 (fail\$3 inadequate)	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 08:14
S46	398	((((power\$3 turn\$3) near3 (on up)) enabl\$3) near6 (deivce back\$up)) near10 (needed necessary required)	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 08:28
S47	67	S46 same (fail\$ inadequate)	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 08:16

EAST Search History

S48	32	S46 near10 (fail\$ inadequate)	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 08:28
S49	17979	((fail\$ inadequate) near6 (primary master))	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 08:28
S50	16599	((((power\$3 turn\$3) near3 (on up)) enabl\$3) near6 (secondary back\$up))	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 08:32
S51	428	S49 same S50	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 08:29
S52	199	S49 near10 S50	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 08:33
S53	55	S52 and clock	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 08:32
S54	4	S52 near10 clock	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 08:29
S55	5745	((power\$3 turn\$3) near3 (on up)) near6 (secondary back\$up)	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 08:44
S56	62	S49 near10 S55	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 08:35
S57	977	((power\$3 turn\$3) near3 (on up)) near6 (secondary back\$up) near10 (fail\$3 inadequate needed necessary required)	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 08:34
S58	56	S49 near10 S55	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 08:35
S59	2	S58 near10 clock	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 08:44

EAST Search History

S60	54	((power\$3 turn\$3) near3 (on up)) near6 ((secondary back\$up) near3 clock)	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 08:46
S61	2	S60 and 713/300-340.ccls.	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 08:45
S62	0	(((power\$3 turn\$3) near3 (on up)) near6 ((secondary back\$up) near3 clock)) same ((failure inadequate) near3 (sensed detected))	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 08:46
S63	0	(((power\$3 turn\$3) near3 (on up)) near6 ((secondary back\$up) near3 clock)) same ((fail\$3 inadequate) near3 (sensed detected))	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 08:46
S64	0	(((power\$3 turn\$3) near3 (on up)) near6 ((secondary back\$up) near3 clock\$)) same ((fail\$3 inadequate) near3 (sensed detected))	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 08:47
S65	5	(((power\$3 turn\$3) near3 (on up)) near6 ((secondary back\$up) near3 clock\$)) near10 (fail\$3 inadequate)	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 08:58
S66	2	(((power\$3 turn\$3) near3 (on up)) near6 ((secondary back\$up) near3 clock\$)) and 713/300-340.ccls.	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 08:58
S67	2	(((power\$3 turn\$3) near3 (on up)) near6 ((slave secondary back\$up) near3 clock\$)) and 713/300-340. ccls.	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 08:58
S68	74	(((power\$3 turn\$3) near3 (on up)) near6 ((slave secondary back\$up) near3 clock\$))	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 08:59
S69	5	(((power\$3 turn\$3) near3 (on up)) near6 ((slave secondary back\$up) near3 clock\$)) near10 (fail\$3 inadequate)	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 09:00
S70	18	(((power\$3 turn\$3) near3 (on up)) near6 ((slave secondary back\$up) adj2 clock\$))	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 09:09
S71	711	(((power\$3 turn\$3) near3 (on up)) near6 (slave secondary back\$up)) near10 (fail\$3 inadequate)	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 09:12

EAST Search History

S72	25	S71 and 713/300-340.ccls.	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 09:10
S73	8	(((power\$3 turn\$3) near3 (on up)) near6 (slave secondary back\$up)) near10 (only near (needed necessary required))	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 09:11
S74	1916	(((power\$3 turn\$3) near3 (down off))) near10 (unneeded unnecessary)	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 09:20
S75	30727	after near6 (back\$up secondary)	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 09:17
S76	0	S74 near10 S75	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 09:16
S77	1	S74 same S75	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 09:16
S78	45	(((power\$3 turn\$3) near3 (down off))) near10 (unneeded unnecessary)) near10 (fail\$3 inadequate)	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 09:43
S79	816	power near6 shed\$4	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 09:31
S80	4	S79 near10 (unneeded unnecessary)	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 09:36
S81	19	S79 and 713/300-340.ccls.	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 09:37
S82	85	S79 near10 (\$needed \$necessary required)	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 09:39
S83	3	S82 and 713/300-340.ccls.	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 09:37

EAST Search History

S84	82	S82 not S81	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 09:38
S85	82	S82 not S81 not S83	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 09:41
S86	0	(S79 near10 (\$needed \$necessary required)) same ((after follow\$3) near3 (fail\$3 inadequate))	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 09:40
S87	18	(S82 not S81 not S83) and g06f\$	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 09:41
S88	1710	((power\$3 turn\$3) near3 (down off)) near10 (\$needed \$necessary required)) near10 (after)	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 09:43
S89	217	((power\$3 turn\$3) near3 (down off)) near10 (\$needed \$necessary required)) and ((back\$up secondary) near10 ((power\$3 turn\$3) near3 (on up)) near10 (back\$up))	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 09:45
S90	14	((power\$3 turn\$3) near3 (down off)) near10 (\$needed \$necessary required)) same ((back\$up secondary) near10 ((power\$3 turn\$3) near3 (on up)) near10 (back\$up))	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 09:47
S91	24620	((power\$3 turn\$3) near3 (down off)) near10 (\$needed \$necessary required))	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 09:47
S92	8322	((power\$3 turn\$3) near3 (down off)) near10 (primary master))	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 09:47
S93	3873209	(\$needed \$necessary required) (after near6 fail\$3)	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 09:48
S94	188	S92 near10 S93	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 09:48

EAST Search History

S95	4	S94 and 713/300-340.ccls.	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 09:49
S96	25	S94 and g06f\$	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 09:49
S97	201	((power\$3 turn\$3) near3 (on up)) near10 (secondary back\$up)) near10 (needed necessary)	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 11:03
S98	9	S97 and "713".clas.	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 11:01
S99	13	((power\$3 turn\$3) near3 (on up)) near10 (secondary back\$up)) near10 ((needed necessary) near3 only)	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 11:03
S100	16	((power\$3 turn\$3) near3 (on up)) near10 (secondary back\$up)) near10 ((needed necessary required) near3 only)	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 11:04
S101	347	((power\$3 turn\$3) near3 (on up)) near10 (secondary back\$up)) near10 (needed necessary required)	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 11:08
S102	59	S101 and g06f\$	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 11:09
S103	63	((power\$3 turn\$3) near3 (on up)) near10 (secondary back\$up)) near10 ((fail\$3 inadequate) near6 (detect\$3 sens\$3))	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 11:08
S104	12	S103 and g06f\$	US-PGPUB; OR USPAT; EPO; IBM_TDB	OFF	2006/09/22 11:09